## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,991,313 B2

: January 31, 2006

Page 1 of 1

**DATED** 

INVENTOR(S) : Masahiko Sasa

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## Title page,

Item [56], References Cited, U.S. PATENT DOCUMENTS, should read as follows:

4,510,510A		4/1985	Terasawa	
4,558,326 A	*	12/1985	Kimura et al.	347/30
5,557,306 A	*	9/1996	Fukushima et al.	347/33
6,145,802	,	11/2000	Nakagaki et al.	248/638
FOREIGN PA	TENT	DOCUMENTS	, should read as follows:	
CN		6501 A	11/1996	
TD.	404	050055 4 4	0.44.000	

CN	1136501 A	11/1996
JР	404070355 A *	3/1992
JP	404080037 A *	3/1992
JP	B2 2703647	10/1997
JP	A 10-138506	5/1998
JP	A 2000-065127	3/2000
JP	A 10-305594	11/1998
JP	A 10-114085	5/1998
JP	A 03-099857	4/1991

## Column 11,

Line 10, claim 5 should read as follows:

5. The ink jet printer according to claim 2, wherein an orifice for exhausting part of the pressurized air is provided in a vicinity of an opposite end of the air supply tube to the air pump.

Signed and Sealed this

Eighteenth Day of April, 2006

JON W. DUDAS Director of the United States Patent and Trademark Office